Appendix B

Telephone Hotline Activity

Contents:

- a) 2013 01 18 DC-G Middle School (1 page).
- b) 2013 01 18 Meadowlark South Plat 2 (1 page).
- c) 2013 01 21 expired NPDES permit (4 pages).
- d) 2013 01 25 & 02 06 DNR Joe Griffin (2 pages).
- e) 2013 03 25 Beaverbrooke West Plat 4 (3 pages).
- f) 2013 04 01 Iowa Health Clinic (2 pages).
- g) 2013 05 08 Beaverbrooke West Plat 3 (6 pages).
- h) 2013 05 08 Beaverbrooke West Plat 8 (3 pages).
- i) 2013 05 21 North Pointe (5 pages).
- j) 2013 05 22 James Pointe Plat 2 (1 page).
- k) 2013 05 22 North Park Estates (2 pages).
- I) 2013 05 23 Beaverbrooke West Plat 8 (1 page).
- m)2013 05 28 Beaverbrooke West Plat 9 (1 page).
- n) 2013 05 28 Silkwood Meadows (1 page).
- o) 2013 08 01 James Pointe Plat 1 (2 pages).
- p) 2013 09 25 Beaverbrooke West Plat 9 (1 pages).
- q) 2013 10 09 Beaverbrooke West Plat 9 (3 pages).
- r) 2013 10 16 Autumn Park Plat 2 (6 pages).
- s) 2013 11 18 James Pointe Plat 2 (2 pages).

Trov		TELEPHO	ONE CONVERSAT	TON RECORD	No
engineering	Date:	2013 01 18	Time: 10:26		ALL IN ALL OUT
ROJECT: DC-G Middle School			SPOKE WITH: FIRM:	Scott Clyce Grimes Bldg Ins	pector
.N. 8630-10H			ADDRESS:		
OX ENG. CALLER: Brandt			PHONE:	515.402.3588	
EFER TO PREVIOUS RECORD NO:					
ubject: Final C.O. and seeding					
Saved under K/!proj/7000/7024-03S/303/Qu School	arterly Inspect	tions/2013 phon	e calls/tele record C	lyce 2013 01 18 DC-G M	liddle
7 min15 sec					
Scott sent several e-mails regarding acceptable for issuing the final C.O.	completion	of the pump	room and want	ting to confirm seed	ing is
Told Scott about sending the school storm water permit that can be sign stabilization. Discussed with Scott that would still thin in the fall and might need some Scott is good with that.	ed and sent like to have	t in because t	he site meets g	eneral acceptance f	or
FOX DISPOSITION:			о рнотосору то от	HER PARTY	
ROUTE TO: file WORK LISTED TO BE SCHEDULED BY:		SENI)	то отнея	
FOLLOW UP REQUIRED BY:		ОТН	ER PARTY TO SEND L	ETTER OF CONFIRMATION	N

Tear		TELEPHONE CONVERSATION RECORD					
engineering	Date:	2013 01 18	Time: 10:44		LL IN LL OUT		
PROJECT: Meadowlark South PUD Plat 2							
P.N. 8630-04G.752		V	ADDRESS:				
FOX ENG. CALLER: Brandt			PHONE:	515.802.5720			
TEFER TO PREVIOUS RECORD NO: Subject: Stockpiling soil at back of cu	rh			A			
Saved under K/!proj/7000/7024-03S/303/Quart		ions/2013 phone	e calls/2013 01 18 7	Tele record Meadowlark PU	JD 2		
Less than 1 minute Andrew called to inform me about Hub to the stockpile.	bell's inte	ention to mov	e the piles this	coming Monday 1.21	.2013		
The weather should be cold enough so	moving t	the piles does	n't create a me	SS.			
He was a bit put-out went he went to what there should have been.	the site th	nis morning a	nd noticed a fev	w more piles there th	at		
I thanked him for the prompt attentio	n and coo	peration by F	lubbell.				
				(20)			
FOX DISPOSITION: ROUTE TO: file		.	РНОТОСОРУ ТО ОТ				
WORK LISTED TO BE SCHEDULED BY: FOLLOW UP REQUIRED BY:		SENI	_	TO OTHER F ETTER OF CONFIRMATION	ARTY		

Zimbra

sbw@foxeng.com

Grimes, IA expired NPDES permit

From: Brandt Williamson <sbw@foxeng.com>

Mon, Jan 21, 2013 12:10 PM

Subject: Grimes, IA expired NPDES permit

1 attachment

To: shanetorres@remax.net

Shane,

It was a pleasure to speak with you.

Attached is the form to complete and send to the DNR for the

expired stormwater permit.

Thanks for your prompt attention to this matter.

Brandt Williamson

FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010 Office | 515.233.0000 | Fax | 515.233.0103

www.foxeng.com

2013 01 21 Novel homes NPDES expired permit ltr.pdf 90 KB



January 21, 2013

Mr. Shane Torres Novel Homes 2795 NE Broadway, Ste 200 Des Moines, Iowa 50xxx

shanetorres@remax.net, 515.202.5894

RE: DNR NPDES General Permit #2, Beaverbrooke West, Plat 3, lot 16 (104 N. 14th St)

Mr. Torres,

A review of the Iowa DNR NPDES General Permit No. 2 for this site (#IA 15052-14832) shows that the permit is expired.

Because this is a house lot and the yard is sodded (stabilized), the permit can be closed.

Please complete the attached Notice of Discontinuation (NoD) form (fill in the stabilization date-could be the date the City issued the certificate of occupancy), sign the form and send it to the DNR.

Please be aware that General Permit #2 requires records to be kept available for DNR inspections for three (3) years after the permit is officially closed.

If you have any questions regarding this letter, contact Brandt Williamson at 515.233.0000, sbw@foxeng.com or cellular phone 515.291.0595.

Thank you for your prompt attention to this matter.

FOX Engineering Associates, Inc.

Brangt Williamson

Enclosure: Notice of Discontinuation DNR form 542-8115

CC: City of Grimes, file

imbra

Zimbra

sbw@foxeng.com

RE: Novel Homes

appired 2-04-2009

From: Scott Clyce <sclyce@ci.grimes.ia.us>

Fri, Jan 18, 2013 07:42 AM

Subject: RE: Novel Homes

@1 attachment

To: 'Brandt Williamson' <sbw@foxeng.com>

15052-14832

Good Morning Brandt,

2795 NE Brosle 200 Shane Torres is or was the President of Novel Homes, they have not built a house in Grimes since 2008. His cell number then was 202-5894.

It looks like he may be working for Remax as a Real Estate Agent his number is 515-276-2872. Now would you use this picture for your professional reference photo? UM dress shirt and maybe a tie... Jeez!



another amond Scott sent tisted 981-0222 as another phone & for Shane

Thanks,

Scott Clyce

shame tries erenway, net 124 NIAT, Lot 16

Building Inspector City of Grimes 101 NE Harvey Street

Grimes. Iowa 50111 Office: 515-986-3036 Cell: 515-402-3588

Email: sclyce@ci.grimes.ia.us Web address: www.grimesiowa.gov

Government's first duty and highest obligation is public safety. --- Arnold Schwarzenegger

From: Brandt Williamson [mailto:sbw@foxeng.com]

Sent: Thursday, January 17, 2013 3:42 PM

To: Scott Clyce

Subject: Novel Homes

Scott,

I am working on cleaning up the list of expired NPDES permits in Grimes.

Novel Homes has an expired G.P. #2 for the homes they constructed in Beaverbrooke West.

Do you know if they are still in business and what the contact information is? DNR shows violation letter was undeliverable and I don't find anything with a business page search.

Appreciate your assistance.

Brandt Williamson

FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010 Office | 515.233.0000 | Fax | 515.233.0103 www.foxeng.com



image001.jpg 5 KB

Trov		TELEPHONE CONVERSATION RECORD					
engineering	Date:	2013 01 25	Time: 16:10	O X CALL			
PROJECT: NPDES permits (expire	SPOKE WITH: J FIRM: C						
P.N. 7024-03S.303			ADDRESS:				
FOX ENG. CALLER: Brandt REFER TO PREVIOUS RECORD NO:			PHONE:				
Subject: Letter of 2013 01 15 regal	rding expire	ed permits	1				
Saved under K/!proj/7000/7024-03S/303/Q	uarterly Inspect	tions/2013 phon	e calls/2012 01 25 tele	record DNR Joe Griffin			
Joe called to discuss the letter I ser Grimes, IA has jurisdiction over					t		
He needs a Notice of Discontinuation	n for each p	ermit					
For the two permits that have a new NoD.	w authorizat	ion number, ¡	olease reference th	ne new number on the	е		
For signing the signing the NoD, th Engineer (full time status) can sign		gn (City Adm	inistrator) or the F	OX acting as the City	,		
Gateway Business Park (Gateway F request, requested additional infor				ized, DNR received			
The two part authorization number second number is when site is auth		nis was fir	st number is wher	n request is received,			
Yes, Ruth Rosdail retired in Octobe Ann worked for a time in the water				ay Ann Hildebrand	l		
Ann's phone number is 281.7820							
FOX DISPOSITION:							
ROUTE TO: file WORK LISTED TO BE SCHEDULED BY:		SENI SENI	PHOTOCOPY TO OTHER	R PARTY TO OTHER PART	ГΥ		
FOLLOW UP REQUIRED BY:		ОТНІ	ER PARTY TO SEND LET	TER OF CONFIRMATION			

Year	TELEPHONE CONVERSATION RECORD						
FOX engineering	Date:	ate: 2013 02 Time: 09:30			CALL IN CALL OUT		
PROJECT: NPDES permits (expired)			SPOKE WITH: FIRM:	Joe Griffin DNR			
P.N. 7024-035.303			ADDRESS:				
FOX ENG. CALLER: Brandt			PHONE:	515.281.7017			
REFER TO PREVIOUS RECORD NO: Subject: 2013 01 29 packette of NoD's	for evn	ired permit	5				
					,		
Saved under K/!proj/7000/7024-03S/303/Quarte							
John called at 09:23, he is in meeting, needs explanation about packette of No	requestir oD's he r	ng I call Joe (eceived	Griffin. John red	ceived call fron	1 Joe who		
Call Joe at 09:30 and talk for minutes,	42 secor	nds.					
He had forgotten about our phone convexpired permits.	versation	of 2013 01 2	25 about letter o	of 2013 01 15	and closing		
Discussed the sites/permits, I, acting of the permits, most were non-responsive liability) to close the permits as lender	e or state	ed they didn't	attempted to ha have responsib	ve the permit oility (wouldn't	holders close take on the		
Those sites listed as stabilized are stab building will require a new permit 3 development, will require a permit.	oilized and Joe clarifi	d finished bu ied that even	ilding or if there a lot less than	e is going to be one acre, if pa	additional rt of a larger		
Joe stated the City cannot technically of and will make notes in the system. It is have to be filed for "active" permits. I reports.	said part	of the reasor	n for closing is s	o quarterly rep	orts don't		
We discussed how there will be closer issue. Should also be better because	attention of fewer	n to permits in developers w	n the future to who will go banki	where this wor rupt.	i't be an		
FOX DISPOSITION: ROUTE TO: file		- 1 📖	О РНОТОСОРУ ТО ОТ				
WORK LISTED TO BE SCHEDULED BY: FOLLOW UP REQUIRED BY:		SENI	O ER PARTY TO SEND I		OTHER PARTY		

RE: track-out in Beaverbrooke West Plat 4

From: Scott Clyce <sclyce@ci.grimes.ia.us>

Mon, Mar 25, 2013 12:32 PM

Subject: RE: track-out in Beaverbrooke West Plat 4

To: 'Brandt Williamson' <sbw@foxeng.com>

Hello Brandt,

What happened there was 1908 NW Calista had there dumpsters changed and the driver tracked mud out and a concrete chunk. A homeowner called City Hall and I contacted Giovanti Homes to clean it up and they took care of it. The first time they came out they only picked up the concrete I had to call a second time to advise that we wanted the mud as well. LOL. So to make a long story short hopefully they realize what needs to be cleaned and the importance of it. J

Thank you for contacting Corell to correct the Corp issue, Plumbers borrowed water from 1904 for our groundworks inspection.

Thanks, Scott Clyce Building Inspector City of Grimes

101 NE Harvey Street Grimes, Iowa 50111 Office: 515-986-3036 Cell: 515-402-3588

Email: sclyce@ci.grimes.ia.us
Web address: www.grimesiowa.gov

Government's first duty and highest obligation is public safety. --- Arnold Schwarzenegger

From: Brandt Williamson [mailto:sbw@foxeng.com]

Sent: Monday, March 25, 2013 11:52 AM

To: Scott Clyce

Subject: track-out in Beaverbrooke West Plat 4

Scott,

Here is a track-out complaint received at the Iowa Storm Water Education Program website that Pat Sauer forwarded to me.

As an FYI, Mark Devine called me last Thursday asking for assistance with a water supply problem at 1908 Calista.

It appeared the corporation at the main hadn't been turned on after the main was tested. When the curb stop was turned on to supply water to the house...ooops..no water. I contacted Corell (utility contractor for Plat 4) and they came out and excavated to turn the corporation valve on.

Not certain who is guilty of the track-out, this lets you know it may not be the usual suspects. Brandt

From: "Pat Sauer" <<u>PSauer@iamu.org</u>>
To: "Brandt Williamson" <<u>sbw@foxeng.com</u>>
Sent: Sunday, March 24, 2013 3:45:49 PM

Subject: FW: New entry added

track-out in Beaverbrooke West Plat 4

From: Brandt Williamson <sbw@foxeng.com>

Mon, Mar 25, 2013 11:51 AM

Subject: track-out in Beaverbrooke West Plat 4

To: Scott Clyce <sclyce@ci.grimes.ia.us>

Scott,

Here is a track-out complaint received at the Iowa Storm Water Education Program website that Pat Sauer forwarded to me.

As an FYI, Mark Devine called me last Thursday asking for assistance with a water supply problem at 1908 Calista.

It appeared the corporation at the main hadn't been turned on after the main was tested.

When the curb stop was turned on to supply water to the house...ooops..no water.

I contracted Coroll (whility contractor for Plat 4) and they came out and excavated to turn to

I contacted Corell (utility contractor for Plat 4) and they came out and excavated to turn the corporation valve on.

Not certain who is guilty of the track-out, this lets you know it may not be the usual suspects. Brandt

From: "Pat Sauer" < PSauer@iamu.org>
To: "Brandt Williamson" < sbw@foxeng.com>
Sent: Sunday, March 24, 2013 3:45:49 PM

Subject: FW: New entry added

Brandt:

We received this complaint on the ISWEP website. Do you handle these for the City of Grimes?

Pat

From: Sauer, Pat

Sent: Tuesday, March 19, 2013 3:55 PM

To: Sauer, Pat

Subject: New entry added

A new CONCERN has been reported:

Report Type: Problem
Report Topic: Mud in Street

Comments: Contractors left mud and concrete in street. They came and picked up the concrete, but the mud is still there.

Location of Concern: Address, City: 2009 NW Calista

Grimes, Iowa 50111

Name: Email: Phone:

Please forward this report to the appropriate contact person immediately.

Brandt:

We received this complaint on the ISWEP website. Do you handle these for the City of Grimes?

Pat

From: Sauer, Pat

Sent: Tuesday, March 19, 2013 3:55 PM

To: Sauer, Pat

Subject: New entry added

A new CONCERN has been reported:

Report Type: Problem
Report Topic: Mud in Street

Comments: Contractors left mud and concrete in street. They came and picked up the concrete, but the mud is

still there.

Location of Concern: Address, City: 2009 NW Calista

Grimes, Iowa 50111

Name: Email: Phone:

Please forward this report to the appropriate contact person immediately.

RE: Iowa Health Clinic-removing erosion controls

From: Joshua A. Wiederholt < JWiederholt@edgeco-usa.com>

Mon, Apr 01, 2013 02:16 PM

Subject: RE: Iowa Health Clinic-removing erosion controls

@4 attachments

To: 'Brandt Williamson' <sbw@foxeng.com>

Cc: Bill J. Herman < BHerman@edgeco-usa.com >

Brandt,

The erosion controls you refer to in the attached letter were removed 3/15/13. If you have questions or concerns, feel free to contact me.

Thank you,

JOSH WIEDERHOLT, LEED AP BD + C

Project Manager

3155 SE Miehe Dr., Ste. 2

EDGE GI

COMPANIES

Grlmes, IA 50111 P: 515/986.2229 x107| F: 515/986.2239 | C: 515/210.2847

www.edgeco-usa.com

COMMERCIAL | HEALTHCARE | INDUSTRIAL

From: Brandt Williamson [mailto:sbw@foxeng.com]

Sent: Friday, January 25, 2013 11:39 AM

To: Joshua A. Wiederholt

Subject: Re: Iowa Health Clinic-removing erosion controls

Josh

The City of grimes greatly appreciates your assistance.

Brandt

From: "Joshua A. Wiederholt" < <u>JWiederholt@edgeco-usa.com</u>>

To: "sbw@foxeng.com" <sbw@foxeng.com>
Cc: "Bill J. Herman" <BHerman@edgeco-usa.com>
Sent: Friday, January 25, 2013 11:38:33 AM

Subject: FW: Iowa Health Clinic-removing erosion controls

Brandt,

We'll get these removed as soon as frost conditions allow us.

Thank you,

JOSH WIEDERHOLT, LEED AP BD + C

Project Manager

3155 SE Miehe Dr., Ste. 2

Grlmes, IA 50111

P: 515/986.2229 x107 | F: 515/986.2239 | C: 515/210.2847

www.edgeco-usa.com

COMMERCIAL | HEALTHCARE | INDUSTRIAL

From: Brandt Williamson [mailto:sbw@foxeng.com]

Sent: Friday, January 25, 2013 10:17 AM

To: Joshua A. Wiederholt

Subject: Iowa Health Clinic-removing erosion controls

Josh,

Please see attached letter and photos regarding removing silt fence at the Iowa Health Clinic site. Thanks

Brandt Williamson

FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010 Office | 515.233.0000 | Fax | 515.233.0103 www.foxeng.com

)+ OB QL CEED, LICHER GERWINKOL

hyddhaga 11999. Afeli, Ge. 1

EDGE GEGERAL IN IMAGE 48 KB COMPANIES WEEDONESCO

CEMENTACIAL | HEALTECARE | INSUSTRUAL

image001.jpg



2013 01 23 Iowa Health Clinic silt fence 2.jpg 877 KB



2013 01 23 Iowa Health Clinic silt fence 1.jpg 830 KB



2013 01 25 Iowa Health signed letter.pdf 27 KB

RE: Storm Water concern

From: Scott Clyce <sclyce@ci.grimes.ia.us>

Subject: RE: Storm Water concern

To: 'Brandt Williamson' <sbw@foxeng.com>

Hello Brandt,

Thank you the address is 1704 NW Morningside Drive you are exactly right Beaverbrook West Plat 3. What time on Monday? 10:0

Thanks,

Mike Chambers 1704 NW Morningside Drive Grimes, Iowa 50111 986-5305 hm 2nd lot north of Beaver brooder Dr. Marningside Dr.

Scott Clyce Building Inspector City of Grimes

101 NE Harvey Street Grimes, Iowa 50111 Office: 515-986-3036 Cell: 515-402-3588

Email: sclyce@ci.grimes.ia.us
Web address: www.grimes.iowa.gov

Government's first duty and highest obligation is public safety. --- Arnold Schwarzenegger

From: Brandt Williamson [mailto:sbw@foxeng.com]

Sent: Wednesday, May 08, 2013 9:31 AM

To: Scott Clyce

Subject: Re: Storm Water concern

Hi Scott,

Monday of next week should work out well.

Is this in Beaverbrooke West Plat 3?

Brandt

From: "Scott Clyce" <sclyce@ci.grimes.ia.us>

To: sbw@foxenq.com

Sent: Wednesday, May 8, 2013 9:16:35 AM

Subject: Storm Water concern



Brandt,

I was asked last night at the P&Z meeting by Mike Chambers a PZ Board Member if we would s direction to assist with the lot drainage issues they are having. (Kind of like we did in North Pc was hoping to visit either Monday or Tuesday if that works for you.

Thanks,

Scott Clyce Building Inspector City of Grimes

101 NE Harvey Street Grimes, Iowa 50111 Office: 515-986-3036 Cell: 515-402-3588

Email: sclyce@ci.grimes.ia.us

Web address: www.grimesiowa.gov

Government's first duty and highest obligation is public safety. --- Arnold Schwarzenegger

The second second

image001.gif 2 KB

Zimbra

Storm Water concern

From: Scott Clyce <sclyce@ci.grimes.ia.us>

Wed, May 08, 2013 09:16 AM

3 attachments

Subject: Storm Water concern

To:sbw@foxeng.com

Brandt,

I was asked last night at the P&Z meeting by Mike Chambers a PZ Board Member if we would stop by his house and look his grading on his lot and adjacent lots to see if we might have any advice or direction to assist with the lot drainage issues they are having. (Kind of like we did in North Pointe) I have attached the pictures but I do not have construction drawing if you could bring those please. I was hoping to visit either Monday or Tuesday if that works for you.

Thanks,

Scott Clyce Building Inspector City of Grimes

101 NE Harvey Street Grimes, Iowa 50111 Office: 515-986-3036 Cell: 515-402-3588

Email: sclyce@ci.grimes.ia.us
Web address: www.grimesiowa.gov

Government's first duty and highest obligation is public safety. --- Arnold Schwarzenegger


And the second

image001.gif 2 KB




DSCN0581.jpg 3 MB

DSCN0583.jpg 3 MB







Year		TELEPHO	NE CONVERSAT	ATION RECORD N			
Lengineering		2013 05 08	Time: 14:42			L IN L OUT	
PROJECT: Beaverbrooke West Plat 8			SPOKE WITH: FIRM:				
P.N. 8630-			ADDRESS:	dillies	Diag Impo		
OX ENG. CALLER: Brandt			PHONE:	515.402	2.3588		
EFER TO PREVIOUS RECORD NO:			Ī				
Subject:							
Saved under K/!proj/7000/7024-03S/303/Quarter 4 min., 45 second call with Scott Clyce & Joe McA Scott called to say the City had been visited by DI part of town. Joe said he went and investigated. The water was property, and didn't see dirty water until opposite It appeared to Joe that all of the controls (silt fend discharge from a localized point. Appears the water	reavey, re NR/Iowa N s clean/cle the sport ce) were i	eturned Scott's volume Waters Program volume ear west of the R s complex. n-place and func d up after an hou	pice mail from 12:3 who were concerned R trestle box culver tioning and that it references.	4 I by brown w t, he went ir may have be	vater in the north at Blake Putney en an isolated		
Joe noticed it appeared the contractor was placing	g sand or	clay (loose mate	rial) on top of surro	unding mate	rial.		
Joe didn't think highly of the two people that cam			h. done				
Told him I would make a site visit and see if there I asked if there needs to be follow-up with the DN	R, he did	ing that needs to n't think so.	be done.				
	į.				v.		
	+				1		
FOX DISPOSITION:							
ROUTE TO: file		.	РНОТОСОРУ ТО ОТ	HER PARTY	TO OTHER DAT	ידע	
WORK LISTED TO BE SCHEDULED BY: FOLLOW UP REQUIRED BY:		- SENI	O ER PARTY TO SEND L	ETTER OF CO	TO OTHER PAF	CIY	

Contact - IDNR

From: Scott Clyce <sclyce@ci.grimes.ia.us>

Wed, May 08, 2013 02:58 PM

3 attachments

Subject : Contact - IDNR

To:sbw@foxeng.com

Hello Brandt,

Her name was Lynette Seigley – IDNR - Project Aware Coordinator – 1-319-335-1598/ 1-319-560-6862

Lynette.seigley@dnr.iowa.gov

I included pictures that they emailed to me.

Thanks,

Scott Clyce Building Inspector City of Grimes

101 NE Harvey Street Grimes, Iowa 50111 Office: 515-986-3036 Cell: 515-402-3588

Email: sclyce@ci.grimes.ia.us
Web address: www.grimesiowa.gov

Government's first duty and highest obligation is public safety. --- Arnold Schwarzenegger

image001.gif 2 KB


2013-05-08 11.59.29.jpg 3 MB



2013-05-08 12.00.05.jpg 4 MB

Scanned Saned to 7024-035.309/photos/ DNR Proper Aware Coordinator





RE: North pointe .. Serious erosion issue.

From: Kelley Brown < kelbrown@ci.grimes.ia.us>

Tue, May 21, 2013 12:15 PM

Subject: RE: North pointe .. Serious erosion issue.

1 attachment

To: 'jeffvaage' <jeffvaage@msn.com>

Cc: 'John Gade (jmg@foxeng.com)' <jmg@foxeng.com>, 'Brandt Williamson

(sbw@foxeng.com)' <sbw@foxeng.com>, Joe McAreavy

<JMcAreavy@ci.grimes.ia.us>

Jeff,

Here is the contact information for the project engineer. Our engineer is reviewing your concerns as well.

Thank you for bringing it to our attention.

Kelley

Matt Heath, E.I.T. Project Engineer



building strong communities

1360 NW 121St Street Clive, Iowa 50325 (515) 964-1229 www.mecresults.com

From: jeffvaage [mailto:jeffvaage@msn.com]

Sent: Tuesday, May 21, 2013 11:25 AM

To: Joe McAreavy; Kelley Brown

Subject: North pointe .. Serious erosion issue.

Joe and Kelly, I wanted to share the results of the contractors solution for erosion control. This level of runoff of soil into our yards is totally unacceptable..please fwd. this to the engineer for the project and pass his contact info to me as I have misplaced his card. I also have video and additional pics. that will be provided to the DNR. Please feel free to provide these to the council, as they are equally culpable.

Jeff Vaage 2405 NE Destination Circle. Grimes..

Sent from my Verizon Wireless 4G LTE Smartphone



image001.jpg

2 KE

Re: North pointe .. Serious erosion issue.

From: John Gade <jmg@foxeng.com>

Tue, May 21, 2013 12:11 PM

Subject: Re: North pointe .. Serious erosion issue.

To: Kelley Brown < kelbrown@ci.grimes.ia.us>

Cc: Mitch Holtz <msh@foxeng.com>, Joe McAreavy

<jmcareavy@ci.grimes.ia.us>, Brandt Williamson (sbw@foxeng.com)

<sbw@foxeng.com>

Kelley,

We will investigate and send you a response. We will forward this to McClure.

Curious if the last photo (chain link fence) is the runoff from the farm fields versus the development.

The runoff water over the silt fence is obviously dirty. It appears it overtopped the silt fence near Mr. Vaage's property. I assume the photo showing the large amount of silt fence overtopping is at the proposed storm water outlet into our park ground. Thus, that runoff is not contributing to Mr. Vaage's property. It appears the silt fence is functioning properly.

The goal is to hold back as much silt as possible. The silt fence should help filter the stormwater runoff. Due to the amount of rain, the silt fence overtopped.

We should investigate to see if there is silt sediment in his property and in our park.

Thanks,

John Gade, P.E.
Director of Municipal Engineering
FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010

Office | 515.233.0000 | Cell | 515.291.2470

www.foxeng.com

From: "Kelley Brown" <kelbrown@ci.grimes.ia.us>

To: "John Gade (jmg@foxeng.com)" <jmg@foxeng.com>, "Mitch Holtz" <msh@foxeng.com>

Sent: Tuesday, May 21, 2013 11:54:22 AM

Subject: FW: North pointe .. Serious erosion issue.

Please review and advise -

Thank you!

From: jeffvaage [mailto:jeffvaage@msn.com]

Sent: Tuesday, May 21, 2013 11:25 AM

To: Joe McAreavy; Kelley Brown

Subject: North pointe .. Serious erosion issue.

Joe and Kelly, I wanted to share the results of the contractors solution for erosion control. This level of runoff of soil into our yards is totally unacceptable..please fwd. this to the engineer for the project and pass his contact info to me as I have misplaced his card. I also have video and additional pics. that will be provided to the DNR. Please feel free to provide these to the council, as they are equally culpable.

Jeff Vaage 2405 NE Destination Circle. Grimes..

Fwd: North pointe .. Serious erosion issue.

From: John Gade <jmg@foxeng.com>

Tue, May 21, 2013 02:04 PM

@1 attachment

Subject: Fwd: North pointe .. Serious erosion issue.

To: Kelley Brown <kelbrown@ci.grimes.ia.us>

Cc : Brandt Williamson (sbw@foxeng.com) <sbw@foxeng.com>, Mitch Holtz <msh@foxeng.com>, Joe McAreavy <jmcareavy@ci.grimes.ia.us>

John Gade, P.E. Director of Municipal Engineering FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010 Office | 515.233.0000 | Cell | 515.291.2470

www.foxeng.com

From: "Matt Heath" < mheath@mecresults.com>

To: "John Gade (jmg@foxeng.com)" <jmg@foxeng.com>

Sent: Tuesday, May 21, 2013 2:02:03 PM

Subject: FW: North pointe .. Serious erosion issue.

Thank you,

Matt Heath, E.I.T. Project Engineer



building strong communities

1360 NW 121st Street Clive, Iowa 50325 (515) 964-1229 www.mecresults.com

From: Darla Maronn [mailto:Darla@stormwateriowa.com]

Sent: Tuesday, May 21, 2013 2:00 PM

To: Heath, Matt

Subject: RE: North pointe .. Serious erosion issue.

Hi Matt,

I was already out there yesterday morning and saw where we are rilling and where fence was failing. I sent pics and contacted Pezzetti Erosion and they were going out to the site to correct the problem. I haven't heard back from them yet but will be following up today and let you know.

Thanks.

Darla

Darla Maronn, CPSWPPP, CCIS Stormwater Management Resources, Inc. PO Box 30214 Des Moines, Iowa 50310 darla@stormwateriowa.com 515-371-6046

From: Heath, Matt [mailto:mheath@mecresults.com]

Sent: Tuesday, May 21, 2013 12:26 PM

To: darla@stormwateriowa.com

Cc: Henter, Kevin

Subject: FW: North pointe .. Serious erosion issue.

Thank you,

Matt Heath, E.I.T. Project Engineer



building strong communities

1360 NW 121st Street Clive, Iowa 50325 (515) 964-1229 www.mecresults.com

From: John Gade [mailto:jmg@foxeng.com]
Sent: Tuesday, May 21, 2013 12:13 PM

To: Heath, Matt

Cc: Brandt Williamson (sbw@foxeng.com); Mitch Holtz; Kelley Brown

Subject: Fwd: North pointe .. Serious erosion issue.

Matt,

Please investigate and send me a response if there is an issue.

I would recommend discussing the issue directly with the property owner since you already discussed the stormwater runoff concerns with them.

Thanks,

John Gade, P.E. Director of Municipal Engineering

FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010 Office | 515.233.0000 | Cell | 515.291.2470 www.foxeng.com

From: jeffvaage [mailto:jeffvaage@msn.com]

Sent: Tuesday, May 21, 2013 11:25 AM

To: Joe McAreavy; Kelley Brown

Subject: North pointe .. Serious erosion issue.

Joe and Kelly, I wanted to share the results of the contractors solution for erosion control. This level of runoff of soil into our yards is totally unacceptable..please fwd. this to the engineer for the project and pass his contact info to me as I have misplaced his card. I also have video and additional pics. that will be provided to the DNR. Please feel free to provide these to the council, as they are equally culpable.

Jeff Vaage 2405 NE Destination Circle. Grimes..

Sent from my Verizon Wireless 4G LTE Smartphone



image001.jpg 2 KB

Tear		TELEPHONE CONVERSATION RECORD				
engineering	Date:	2012 05 22	Time: 14:30	CALL IN CALL OUT		
ROJECT: James Pointe, Plat 1			SPOKE WITH:			
James Fornte, Flat 1			FIRM:			
N. 8630-06B			ADDRESS:			
OX ENG. CALLER: Brandt			PHONE:			
EFER TO PREVIOUS RECORD NO:						
ubject: Sidewalk grading in lot 13						
Saved under K/!proj/8000/8630-06B/Erosion, Met Scott Clyce (Grimes bldg inspector) and I certificate of occupancy. Took two photos. N	Dave Albright (homebuilder) at	the site to discuss site gra	ading prior to issuing		
Sidewalk appears to be constructed according design. Yes, water will be trapped on lot 12 presented to the homeowner sooner than late Mr. Albright asked if is alright to stabilize the adjacent landowner latter? Yes. Adjacent pro In order to get the water to drain may grade draining to east as shown on the plans.	(house was bui er. yard to acquir operty owner n	ilt by Vic Mitchel e the C.O. and v nay want to rem	l-Mater Crafted Homes, In vait to stabilize the side of ove chain link fence to gra	the sidewalk common with de the site.		
There will probably be another site meeting with the homeowners and not a matter for the cit	with lot 12 own y to enforce/re	er and homebui solve.	lder. It was stressed that	this is a civil issue between		
Walked with Mr. Albright around the house a drainage away from the house.	nd pointed out	several areas th	aat he may want to re-grad	de to provide better		
FOY DISPOSITION!						
	প্ৰ	CENT	D BUOTOCOBY TO OTHER DA	PTV		
FOX DISPOSITION: ROUTE TO: WORK LISTED TO BE SCHEDULED BY:		SENI	D PHOTOCOPY TO OTHER PA	RTY TO OTHER PARTY		

Year	-		TELEPHONE CONVERSATION RECORD N						
FOX engine	eering		Date:	2013 05 22	Time:	08:43		x	CALL IN CALL OUT
ROJECT:	North I	Park Estates, Grimes	, IA		SPOKI		Jeff Pezzett		n Control, Inc.
.N.	8630-	-13D			AD	DRESS:		niversity	Ave., Ste 220
OX ENG. C		Brandt RECORD NO:				PHONE:		<u></u>	
		maintenance and sec	diment	remediation	1				
Saved und	ler K/!proj/7	7000/7024-03S/Complaints 8	k Spills/20	013 05 21/2013	05 22 tele	e record P	ezzetti		
	s 6 seconds								
He intends He receive owner. Darla rece	to be there d one phote lived clearar	It if he has a schedule for site e tomorrow, assuming it does o from Darla (Stormwater Mance from the owner to perfor e site for the initial control in	sn't rain r anagemer m mainte	nuch so the site It Resources, Inc Inance to the silt	fence an	d install ac	dditional c	ontrol &	passed the info
the two hi	ah pressure	e site for the initial control in e gas mains (4" diameter) thi : fence as close to the engine	at were m	nore or less expo	sed (stick	ting out of	the grou	nd).	
		hree locations that should be							
location. That ever	Told him that It may have	e site may need to have addi se rain gauge at the North Sp been less than one hour du d for approximately 0.50" pre	orts Com ration whi	plex registered 1 ich means the co	50" of p	recipitatio:	n from Mic	onday's r	ain event.
Jeff said l approved	ne heard the by the City	e project is on hold and aske (FOX) . A comment letter w	d if I knev as sent to	w whyprobably the design engi	because neer earli	the constr er this we	ruction pla ek.	ins have	not been
Sent JMG	an e-mail a	at 09:38 with yesterday's ph	otos and f	today's conversa	tion with	Jeff Pezze	tti.		
that ease Mitch wa been con	ment witho s copied on tacted. Mit	n about the exposed gas main but permission from the gas of the e-mails about the erosion ch agrees control wasn't inte gineer about getting plans ap	company. n problen ended to h	Grading contraction. Home owner mandle the intens	tor cease threatene	d operations of the contraction	info to Di	easemei NR, impli	es DNR hasn't
FOX DISPO				CEN	D BUOTO	COPY TO O	LHEB DVD.		
	ISTED TO BI	ile E SCHEDULED BY:		SEN	D			TC	OTHER PARTY
FOLLOW	UP REQUIF	RED BY:		_ OTH	ER PARTY	TO SEND	LETTER O	r CONFIR	MATION

Re: North Park

From: Brandt Williamson <sbw@foxeng.com>

Wed, May 22, 2013 09:38 AM

Subject: Re: North Park

4 attachments

To: John Gade <jmg@foxeng.com>

John,

Here are photos of the site from 5.21.2013 at 4:00 p.m.

Very little sediment appears to have collected in the drainage easement of the property owners. The FOX rain gauge at the North Sports Complex had 1.50" of precipitation from Monday's storm.

I talked with Jeff Pezzetti this a.m. (installed the silt fence) about timeline to repair the silt fence. It is his intention to have a crew at the site tomorrow (after it dries up a little) to remove sediment build-up from the silt fence and install additional control.

They will also remove sediment that has migrated past the silt fence.

There are three locations where silt fence needs attention.

1 major for sediment (east end of site)

1 minor for sediment (near east end of site)

1 minor for silt fence that was over-topped without sediment migration (near west end)

Jeff commented there are two 4-inch high pressure gas mains in the area of the major sediment migration that prevented him from installing silt fence.

He said the gas mains are more or less exposed at that location.

Is there a concern about the burial depth of the gas mains the City should follow-up on?

Brandt

From: "John Gade" <jmg@foxeng.com>

To: sbw@foxeng.com

Sent: Tuesday, May 21, 2013 7:11:51 PM

Subject: North Park

Any update or photos?

John Gade, P.E.
Director of Municipal Engineering
FOX Engineering Associates, Inc.
414 South 17th Street, Suite 107
Ames, Iowa state 50010
O 515.233.0000
C 515.291.2470



IMG_4722.JPG 2 MB

Zimbra

RE: Beaverbrooke West Plat 8 trackout

From: Dave Hyler <dhyler@ecincorp.com>

Thu, May 23, 2013 03:39 PM

imparimentationoug.com amora in primenopage are 20.00

Subject: RE: Beaverbrooke West Plat 8 trackout

To: Steve Moyna <steve.moyna@eldercorp.com>, Brandt Williamson <sbw@foxeng.com>

Cc: John Gade (E-mail) <jgade@foxeng.com>, Joe McAreavy <jmcareavy@ci.grimes.ia.us>, Dave Nethers <dhn@foxeng.com>

By the end of the day we will have the street cleaned up, the driveway swept off, the intake baskets at the end of the street cleaned out and 3 runs of silt fence installed at the end of the road to help keep the road shut off to traffic and also prevent sediment from reaching the old rock Cul-De-Sac. Thanks

Environmental Consultants, Inc. Dave Hyler 515-490-7344 dhyler@ecincorp.com

From: Steve Moyna [mailto:steve.moyna@eldercorp.com]

Sent: Thursday, May 23, 2013 10:34 AM

To: Brandt Williamson

Cc: John Gade (E-mail); Joe McAreavy; Dave Nethers; Dave Hyler

Subject: Re: Beaverbrooke West Plat 8 trackout

Please include Hyler on these items also, as they are handling the erosion control for the project. He is handing to the site this afternoon. Thanks

Sent from my iPad

On May 23, 2013, at 10:15 AM, "Brandt Williamson" < sbw@foxeng.com > wrote:

Steve,

The City has received a complaint about track-out onto NW Gabus Drive from the rock cul-de-sac

that is being utilized as the construction access for this subdivision.

Please have the roadway cleaned up ASAP.

Also, it sounds as though the rock entrance needs additional aggregate.

Feel free to call me about this matter.

Brandt Williamson

FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010

Office | 515.233.0000 | Fax | 515.233.0103 www.foxeng.com

Years	TELEPHONE CONVERSATION RECORD					
FOX engineering	Date: 2013 05	Time: 15:05	CALL IN CALL OUT			
ROJECT: Beaverbrook West Plat 9	FIRM:	Scott Clyce Grimes Bldg Inspector				
P.N. 8630-98D.751		ADDRESS:				
FOX ENG. CALLER: Brandt		PHONE:	515.402.3588			
REFER TO PREVIOUS RECORD NO:						
Subject: Silt fence post danger to adjace	cent homeowner	children				
Saved under K/!proj/7000/7024-03S/303/Quarter Scott Clyce calls me and we speak for 5.5 minutes Homeowner has concern about the newly installed Scott has been to the site and notes there is a soo Silt fence is on Plat 9 (Gabus) property. Scott talked with the homeowner for at least 10 m and Scott thinks this could be a long term probler We discuss protective caps, tell him about the hor I will go look at the site. Called David Bentz (515) 473 – 0499 at 16:05, w the site. Tell him this is a heads up to a potential neighbor, however, there are usually strict expect children. Pointed out the silt fence is installed pe I e-mailed him a photo of the site, I missed his capointed out the soccer goal is on private property Wednesday 5.29.2013, 08:17, 10 minutes 31 sec I call Scott Clyce and tell him about site visit and homeowner installing protective caps on the post We also discussed the Silkwood Meadows site – I	s about homeowner at 5 d silt fence as being a datcer goal next to the silt ninutes about the situation if ignored (i.e. homeownemade ones used at R while driving to the site, to problem. He says that tations about the require rerosion requirements. The sall at 17:20 and returned in the conds discussion with David B is	04 NW 13 th (BB Westinger to his children (fence.) on, the homeowner was when would contact Ginggenberg her in Amico alert him to situation Gabus might install sements. Should be upon the call at 17:31 we city about having the entz. Scott will call to	Plat 2) (impaling on post?) vas adamant about child safety (abus directly) nes that cost \$3.00 to make. on, he requests a photograph of safety caps as for being a god p to the homeowner to protect e talked for almost 4 minutes. He homeowner install protection.			
FOX DISPOSITION:						
FOX DISPOSITION: ROUTE TO: WORK LISTED TO BE SCHEDULED BY:		END PHOTOCOPY TO O	THER PARTY TO OTHER PARTY			

7	TELEPHONE CONVERSATION RECORD					
FOX engineering	Date:	2013.05.28	Time: 14:30		X CALL	
ROJECT: Silkwood Meadows, Plat 1			SPOKE WITH:	actor		
			ADDRESS:	City of Gri	Jector	
P.N. 8630-13A.750 FOX ENG. CALLER: Brandt			PHONE:	515.402.358	88	
REFER TO PREVIOUS RECORD NO:			I HONE.	313.402.330		
Subject: Topsoil stockpile in SW corner of site						
14:30, 10 minutes 45 seconds Scott Clyce called to voice concern abou Contractor has begun site grading and ti This is the last house (south end) on we His concern is lack of control around pile Told him I would take a look at it. This Perimeter control should be established. Arrive at site around 6:10 p.m., take 3 what is going on, he was relieved to know about property values). Discussed to podirection the new subdivision will flow, so 05 29 2013, 08:05, call Scott Clyce and the stockpile at this time, however, pericontractor about it.	here is st side to pre is first to photos, ow the suspect	a soil stockpil of Silkwood Devent soil from I have heard talk with the new subdivisiting in his bases some of his your about visiting	le very close to prive from North migrating to the they are gradin adjacent properties all single fack yard, told his ard should draining the site. I definite the training the site. I definite the training the site.	a house. In Point Plat the establish g the site. Entry owner, family resid im not certain. on't see a b	Josh, about ences (conc ain which	with
,						
FOX DISPOSITION: ROUTE TO: File 8630-13A.750 WORK LISTED TO BE SCHEDULED BY: FOLLOW UP REQUIRED BY:		SEN	D PHOTOCOPY TO O		TO OTHER PA	ARTY

@1 attachment

Thu, Aug 01, 2013 09:06 PM

James Pointe Plat 1 sidewalk grading issue

From: Brandt Williamson <sbw@foxeng.com>

Subject: James Pointe Plat 1 sidewalk grading Issue

To: Joe McAreavy <jmcareavy@ci.grlmes.la.us>

Cc: John Gade (E-mail) <jgade@foxeng.com>


Here Is the grading plan sheet (4 of 7) from the approved construction plans for James Pointe Plat 1. For the sidewalk between lots 13 & 14, the water is supposed to drain away from the sidewalk, across the lots.

Scott Clyce and I met with the homebullder for lot 13 on 5.22.2012 to discuss grading the sidewalk. That homebullder was responsible for installing the sidewalk and could see water was going to pond in the adjacent lot.

Brandt Williamson FOX Engineering Associates, Inc. 414 South 17th Street | Sulte 107 | Ames, IA 50010 Office | 515.233.0000 | Fax | 515.233.0103 www.foxeng.com

James Poine Plat 1 grading plan.pdf 192 KB

reid "Mands" reply from gWZs
later this night.



7	TELEPHONE CONVERSATION RECORD					
FOX engineering	Date:	2013.09.25	Time: 09:18 X CALL IN CALL OU			
PROJECT: Beaverbrooke West, Plat 9			SPOKE WITH: Tim FIRM: Elder Corp.			
P.N. 8630-98D.759		ADDRESS:				
FOX ENG. CALLER: Brandt			PHONE: 515.249.1453			
REFER TO PREVIOUS RECORD NO:						
Subject: Sediment in streets 13th & Norton						
about straw clean-up being on 8 th Street 08:03 I called and left voice mail for Tim Site visits to BB West Plats 8 & 9 and Au 11 th & Norton has thin layer of sediment if the sediment. Odd to find a significan sac at the east end of 14 th Street and no There is some straw accumulation at the	the cleat not 11 mot 11	an-up. Scott th. Elder. Park Plat 2 to intersection, ne of sedimen ent in the gui	review sediment conditions. appears the City may have removed sometat the curb intakes next to the cul-detters to indicate from where it migrated.			
	Tim (yes tacted a	s, extremely bout erosion	busy), Dave Hyler 515.490.7344 with concerns regarding BB Plats 3, 4, 8 & 9 w-up with phone call (leave voice mail) at	t		
the site later today. They are having dibuilt. He knows the topsoil stockpile is re-spread. Told him about the sediment controls placed across road tie-ins until roadways are paved. Told him my constorm water to the WWTP and that the	ifficultie an issunt in the the new cern aborcesting o be cor	es getting the e for the norte streets that we roads are pout the sanitations should get and empleted and e	also talk with Dave Hyler. Tim will be at detention pond stabilized and structure th end and they are looking to get the pile needs to be cleaned up. Also need to ha paved. It could be a month before ary castings acting as a direct conduit for sealed up. Also questioned when the store east side of Plat 9 so that stormwater is	e ive		
cleaned some sediment from Gabus Dr from the homebuilders and he didn't cl and will look at the cul-de-sac south of	and Ca ean tha Norton	alista. He not at up. He will a on 14 th . He	Id made a pass thru BB West Plats 3/4 and ted that some of the sediment on Calista is clean up the intersection of 11 th & Norton was surprised to learn the controls off the will look into replacing them (said they	ıs n		
FOX DISPOSITION: ROUTE TO: File 8630-98D.759 WORK LISTED TO BE SCHEDULED BY: FOLLOW UP REQUIRED BY:		- SEN	ND PHOTOCOPY TO OTHER PARTY ND TO OTHER PARTY HER PARTY TO SEND LETTER OF CONFIRMATION	Υ		

Fwd: NPDES

From: Brandt Williamson < sbw@foxeng.com>

Wed, Oct 09, 2013 12:16 PM

mhail firminianter Prantic minner of a Laminiana Paris and a

1 attachment

Subject: Fwd: NPDES

To: dhyler@ecincorp.com

Dave,

Please review the status of the control at 13th Street for Beaverbrooke West Plat 9. Lest voice mail fox Dave e 12:16 10-09-13 515.490.7344

Thanks Brandt

From: "Brandt Williamson" <sbw@foxeng.com>

To: "Kerry Nelsen" < Kerry. Nelsen@RyanCompanies.com>

Sent: Wednesday, October 9, 2013 12:13:05 PM

Subject: Re: NPDES

Kerry,

I will call the erosion contractor now about installing control at the 13th Street entrance.

Brandt

From: "Kerry Nelsen" < Kerry. Nelsen@RyanCompanies.com>

To: "Brandt Williamson" <sbw@foxeng.com> Sent: Wednesday, October 9, 2013 11:53:19 AM

Subject: RE: NPDES

At the entrance on NW 13th it does not appear that silt fences are in place; without fences, socks or gravel, runoff will continue. Have they corrected this?

I appreciate their efforts to clean the streets and understand that once it dries it is difficult to remove. I am more concerned about future runoff.

Thank you for responding to my email.

Kerry Nelsen | Office Manager

Ryan Companies US, Inc. | 14001 University Avenue, Suite 300, Clive, IA 50325

515-309-8526 tel | 515-309-8576 fax

kerry.nelsen@ryancompanies.com

Find us on: The Web | Twitter | Facebook

From: Brandt Williamson [mailto:sbw@foxeng.com] Sent: Wednesday, October 09, 2013 11:47 AM

To: Joe McAreavy; Kerry Nelsen

Cc: John Gade (E-mail) Subject: Re: NPDES

Mr. Nelsen,

Thank you for bringing your stormwater concerns to the attention of the City.

Please know the City takes stormwater matters seriously.

The City has been in contract with both the grading contractor and the erosion control contractor about the volume of sediment leaving the site.

Calls were placed two weeks ago, after the heavy rainfall event, and again last Friday morning about removing sediment from the intersection of 13th & Norton and the cul-de-sac of 14th Street.

Some of the sediment was removed on Friday (Oct. 4th).

A more thorough job of removing sediment was performed Monday (October 7th) starting at 8:00 a.m.

At 9:00 a.m., on the 7th, I met the foreman of the erosion company at the 14th Street location to discuss removal efforts and preventing future occurrences.

The contractor was using flat shovels and brooms to remove sediment in the street. He commented that the grading contractor had provided a mechanical broom earlier that morning and wasn't able to pickup all of the sediment.

The erosion contractor removed most of the sediment and said he would return to the site, at a later date, to work on removing remainder of sediment the flat shovels were having difficulty loosening.

The erosion contractor has a clear understanding about preventing sediment migration from the construction site and has increased the quantity of control.

It should be noted that the last two rain events were in excess of two (2") inches of rainfall in a short period of time which is difficult to control.

The erosion contractor acknowledges it is their responsibility to quickly respond to sediment discharges that exceed the capacity of the controls.

Feel free to contract me if you want additional information about this matter.

Brandt Williamson FOX Engineering Associates cellular phone # (515) 291 0595

From: "Joe McAreavy" < JMcAreavy@ci.grimes.ia.us>

To: "Brandt Williamsen" <<u>sbw@foxeng.com</u>> **Sent:** Wednesday, October 9, 2013 8:32:04 AM

Subject: Fwd: NPDES

This is regarding Beaverbrook west 8&9

Begin forwarded message:

From: Kerry Nelsen < Kerry.Nelsen@RyanCompanies.com >

Date: October 9, 2013 at 8:23:32 AM CDT

To: "Joe McAreavy (<u>JMcAreavy@ci.grimes.ia.us</u>)" < <u>JMcAreavy@ci.grimes.ia.us</u>>

Subject: NPDES

Hi Joe – I'm concerned about the lack of erosion control on the residential project at the west end of NW $13^{\mbox{th}}$ Street. They do not have erosion control barriers or gravel to stop the runoff. This is a concern to me as the last two rains we have had, have resulted in large amounts of mud building up on my street. The runoff is going east on NW $13^{\mbox{th}}$, turning


north on Norton, and east on NW 14th where it puddles at the opening of the cul de sac. This has not been cleaned up by whoever is responsible for the work on the development and it needs to be addressed. We are expecting rain again over the weekend and I do not want even more mud on our street. My car looks like I live on a gravel road. I am familiar with the NPDES requirements as part of my job, and they are not complying. Will you please address this? Thank you.

TIPPO!! TIMIT: FOITOID OUT MITTOL OF PETITOTION DO ! TO OF

Kerry Nelsen | Office Manager
Ryan Companies US, Inc. | 14001 University Avenue, Suite 300, Clive, IA 50325
515-309-8526 tel | 515-309-8576 fax
kerry.nelsen@ryancompanies.com

RY

Find us on: The Web | Twitter | Facebook



sbw@foxeng.com

Re: Autumn Park track-out

From: Brandt Williamson <sbw@foxeng.com>

Wed, Oct 16, 2013 04:37 PM

Subject: Re: Autumn Park track-out

To: Scott Temple <scott@vistarei.com>

Scott,

Saw the photo....thanks.

What with the public being better educated about site erosion and therefore calling City Hall about trackout,

the City has to stay on top of it so the DNR doesn't get involved.

Homeowner did call the DNR earlier this year about an active site.

Also, a different site has used shovels to remove sediment from the street.. and I have followed up with the homeowner about it.

Doesn't ease you financial pain, simply showing there are others that are held accountable too.

Brandt

From: "Scott Temple" <scott@vistarei.com>
To: "Brandt Williamson" <sbw@foxeng.com>
Sent: Wednesday, October 16, 2013 3:34:12 PM

Subject: Re: Autumn Park track-out

So like all other aspects of life (banks etc.) if you follow the rules you are penalized. Speed costs money for someone else's failures. This business is starting to suck.

Scott L. Temple Vista Real Estate 2400 86th Street, Ste 24 Urbandale, IA 50322 Office 515-276-3456 Fax 515-276-2337 Cell 515-202-3173

On Oct 16, 2013, at 1:13 PM, "Brandt Williamson" < sbw@foxeng.com> wrote:

Scott,

The City thanks you for the prompt response.

Looking at the City of Grimes Code - Chapter 102 Stormwater Management and Erosion and Sediment Control ordinance,

paragraph 102.04.7, the last two sentences of the paragraph state...

"Any soils tracked off site shall be cleaned up by the permittee at the end of each day or before sediments enter public storm sewer

or waters of the state. Any soils entering public storm sewer or waters of the state will be in violation of this ordinance."

While "immediately" may seem a bit harsh, it has been necessary to take a hard stance towards other builders who aren't as responsive to the City's requests.

Brandt

From: "Scott Temple" < scott@vistarei.com To: "Brandt Williamson" < sbw@foxeng.com Co: "Nate Hotopp" < nate@vistarei.com>

Sent: Wednesday, October 16, 2013 12:24:45 PM

Subject: RE: Autumn Park track-out

Speck and our guy will be there at three today. Does the city have different rules than the dnr as they give us 48 hours to respond by law. Immediately seems awfully harsh as the city takes weeks to respond to almost everything.

From: Brandt Williamson [mailto:sbw@foxenq.com]
Sent: Wednesday, October 16, 2013 11:35 AM

To: Scott Temple Cc: Scott Clyce

Subject: Autumn Park track-out

Scott,

The City is receiving complaints about track-out from the Autumn Park Subdivisions - Plats 1, 2 & 3.

Please have the streets cleaned today.

The City Building Inspector (Scott Clyce) has been to the site and comments that trackout from Plat 3

through Plat 1 is excessive on Sunset Lane following onto Brookside Drive and needs to be addressed immediately.

A FOX RPR (Mark Wilson) has also been to the sites and confirmed the trackout violation(s).

The streets in Plat 2 have sediment from construction activity that is getting tracked out on 8th Street to James Street.

It appears a majority of the sediment is from utility contractors.

City views the utility contractors as a developers responsibility.

Because the utility contractors have mostly completed their work, after you have the streets cleaned,

the City will look to the homebuilders for future track-out violations.

The City appreciates your cooperation in keeping the streets clean.

Brandt Williamson

FOX Engineering Associates, Inc.

414 South 17th Street | Suite 107 | Ames, IA 50010 Office | 515.233.0000 | Fax | 515.233.0103 www.foxeng.com

sbw@foxeng.com

Fwd: Autumn Park Plat 2 street photo

From: Brandt Williamson <sbw@foxeng.com>

Wed, Oct 16, 2013 04:45 PM

2 attachments

Subject: Fwd: Autumn Park Plat 2 street photo

To: Scott Clyce <sclyce@ci.grimes.ia.us> **Cc**: Scott Temple <scott@vistarei.com>

Scott Clyce,

FYI

Scott Temple hired Spec Enterprises to sweep the roadway in Autumn Park Plat 2.

They completed the work this afternoon.

Shortly after the roadway was cleaned one of the homebuilders tracked out onto the street.

Thought you should know the Developer promptly responded to the City's request.

Brandt

From: "Scott Temple" <scott@vistarei.com>

To: "Williamson Brandt" <sbw@foxeng.com>, "Nate Hotopp" <nate@vistarei.com>

Sent: Wednesday, October 16, 2013 4:30:41 PM

Subject: Auto park two

Five minutes after sweep sure is cost effective put ble where it goes and costs



photo.JPG 108 KB

A

ATT00001.txt 171 B

Year	TELEPHONE CONVERSATION RECORD					
Lengineering	Date: 2013 10 29	Time: 08:52	CALL IN CALL OUT			
PROJECT: Autumn Park, Plat 3			t Temple a Real Estate			
P.N. 8630-06K.703		ADDRESS:				
FOX ENG. CALLER: Brandt		PHONE: 515.	202.3173			
REFER TO PREVIOUS RECORD NO:						
Subject: Erosion control						
Left voice mail for Scott Temple wanted	to discuss need to	stabilize the site, espe	cially the box culvert.			
11:58 Scott returns my call and leaves v	oice mail.					
Thursday 11.07.2013, approx. 9:30 a.m. 0.0 8630-06K.752 Autumn Park Plat 2 (39 lots) — talk with Scott Temple at the Plat 3 site, he intends to haul in 25,000 c.y. of soil and stockpile west of this plat for the next development, not certain if he will develop west of Plat 2 first or West of Plat 3, he knows he will have to refresh the aggregate turn-around when there is too much track-out, discussed the barricades that are supposed to get placed at the end of the temporary turn-around-Scott doesn't see them getting installed because will block hauling to west of the plat, after talking with Scott make site visit to verify the TRM was installed (yes), notice what Scott said about Mid American not completing the light pole installations 1.0 5 T 8630-06K.753 Autumn Park Plat 3 (57 lots) — sit at site and talk with Scott Temple, he has call in to Britt Sternquist about paving the connecting trail to the east, expressed my concern about getting the creek bank stabilized, Sternquist is paving the cul-de-sac that had to be replaced due to rain damage, not certain how soon they will be ready for walk-thru and punchlist, he wonders if Mid Am will be prompt in installing facilities,						
FOX DISPOSITION: ROUTE TO: file WORK LISTED TO BE SCHEDULED BY: FOLLOW UP REQUIRED BY:	SI	END PHOTOCOPY TO OTHER PA END THER PARTY TO SEND LETTER	TO OTHER PARTY			

sbw@foxeng.com

FW: IMG_0453.jpg

From: Scott Clyce <sclyce@ci.grimes.ia.us>

Thu, Oct 17, 2013 08:32 AM

2 attachments

Subject: FW: IMG_0453.jpg

To: sbw@foxeng.com

Cc: Dave Sigler <dsigler@ci.grimes.ia.us>

Brandt,

Here are pictures from this morning where it appears that we have more track out from Plat work at Autumn Park P2, I am not sure if they have a stabilized rock driveway entrance to slow some of this down. actually Plat 3 8630-06K1753

Scott Clyce Building Inspector City of Grimes

101 NE Harvey Street Grimes, Iowa 50111 Office: 515-986-3036 515-402-3588 Cell:

Email: sclyce@ci.grimes.ia.us <mailto:sclyce@ci.grimes.ia.us>

Web address: www.grimesiowa.gov

Government's first duty and highest obligation is public safety. --- Arnold Schwarzenegger

----Original Message----

From: Scott Clyce

Sent: Thursday, October 17, 2013 8:17 AM

To: Scott Clyce


Subject: IMG_0453.jpg



IMG 0453.jpg 318 KB

ATT00001.txt





VICINITY SKETCH

SCALE: 1"=2000'

FINAL PLAT

JAMES POINTE

PLAT 2

OWNER/DEVELOPER

Dec 10: 024986050012 Type: PLT Kind: PLAT Recorded: 08/03/2011 at 08:32:12 AM Fse Amt: 887.00 Page 1 of 12 Polk County Iowa JULIE M. HAGGERTY RECOMDER Files 2012-00006720 ×13928 ≈450·461

GRIMES LAND CO., LLC P.O. BOX 42213 URBANDALE, IOMA 50323

ZONING

R2-60 SINGLE AND TWO FAMILY DWELLING DISTRICT - 60' LOTS

LAND USE

EXISTING: VACANT PROPOSED: SINGLE FAMILY RESIDENTIAL

SETBACKS FRONT - 30' SIDE - 7' MIN. (14' TOTAL) - 1 & 1½ STORY 7' MIN. (15' TOTAL) - 2 & 3 STORY REAR - 25'

LEGAL DESCRIPTION

Parcel 'A' of the Plat of Survey of Outlot Z', James Point, an Official Plat, Grimes, Polk County, Jouo, recorded at Book 13872 Page 443 at the Polk County Recorder's office.

Said tract of land subject to all easements of record.

Said tract of land contains 8,647 acres more or less.

NOTES
1. LOT 'A' TO BE DEDICATED TO THE CITY OF GRIMES FOR STREET PURPOSES.
2 INDIVIDUAL DEIVEWAYS FROM LOTE 1 AND 20 ARE NOT

25th COURT

924.00 924.00 927,00 928,00 926,00 926,00 924.00 923.00 921.85 921.85 921.85 921.85 921.85 921.85 921.85 921.85

MINIMUM PROTECTION

ELEVATION

Szott Chice drainsage consultation 2608 NW Morningside * Mileo Chambers house afterwards Monday 11-18-13 e 08:00 Babe 402-290-7621

			CURVE 1			
CURVE	DELTA	RADIU5	LENGTH		400	
CI	90'00'00"	200.00	314.16	200.00	282.84	N45'04'39"W
C2	90'00'00*	25.00	39,27	25.00	35.36	N45'04'39"W
C3	7'30'20"	230.00	30.13	15.09	30.11	586'19'29"E
C4	14'21'41"	230.00	57.65	28.98	57.50	575*23'29'E
C5	14"12"48"	230.00	57.06	28.67	56.91	561'06'14"E
C6	14'31'30"	230.00	58.31	29.31	58.15	546°44'05°E
C7	_15°45'43"	230.00	63,27	31.64	63.07	531°35'28"E
CB	15'46'38"	230.00	63,33	31.87	63.13	515*49'17"E
C9	7'51'19"	230.00	31.53	15.79	31,51	504'00'19"E
C10	90"07"00"	25.00	39.32	25.05	35.39	N45°08'09"W
CII	89"53'00"	25.00	39.22	24.95	35.32	544°51'51"W
CI2	23*37'57*	170.00	70.12	35.57	69.62	511'53'38'E
CI3	49'42'40"	170.00	147.50	78.75	142.91	548'33'56'E
CI4	16°39'23"	170.00	49.42	24.89	49.25	581°44'58'E
CIE	antonioni	25.00	20.07	25 00	35 37	114 4mm = 1m , 4m





Off LICENSE RENEWAL DATE IS DECEMBER 31, 2012
PAGES OR SHEETS COVERED BY THIS SEAL.
This sheet only

Cooper Crawford

& ASSOCIATES, L.L.C. CIVIL ENGINEERS

475 S. 50th STREET, SUITE 800, WEST DES MOINES, IOWA 50265 PHONE: (515) 224-1344 FAX: (515) 224-1345 DATE: 46-2011 REVISIONS: 615-2011 JOB NUME

SCALE: 1"=60"

CC

JOB NUMBER

FINAL PLAT JAMES POINTE PLAT 2

1 OF 1

Year	TELEPHONE CONVERSATION RECORD No.					
Lengineering	Date:	2013 11 18	Time: 08:00	CAL CAL	L IN L OUT	
PROJECT: James Pointe Plat 2			SPOKE WITH: FIRM:			
P.N. 8630-06B.752			ADDRESS:			
FOX ENG. CALLER: Brandt			PHONE:	515.402.3588		
REFER TO PREVIOUS RECORD NO:						
Subject: Storm water drainage between	n neigh	bors				
Saved under K/!proj/8000/8630-06B/752/2013 11			a with Scott Cl	vco, concern is how to	ang.	
meet homeowner (Blake) at 2608 NW M stormwater sits in his yard, 3 houses aw protecting the intake), Blake is attempti was resolution and then mgmt changed most of the relief he needs, would requifollow-thru with that, he asked if the Cit support	ay is th ng to re hands s re coope	e beehive into solve the issum o no progress eration of sev	ake (I removed be with homebu s, re-grading the eral neighbors,	the silt fence that wa ilder (CSI), thought the e swale would provide sounds as though he	s still here e will	
FOX DISPOSITION:						
ROUTE TO: file			РНОТОСОРУ ТО ОТН			
WORK LISTED TO BE SCHEDULED BY: FOLLOW UP REQUIRED BY:		SEND	R PARTY TO SEND LE	TO OTHER PA	.RTY	